

## Skis - Cont.

### All Skis Are Black Enamel

Wear Rod Not Included



#### SKI DOO

Replaces 505-0628-00  
117 mm. wide



Replaces ski used on Formula Mach (all) 1989-93; Formula MX (all Except XTCR) 1985-93; Formula Plus (all) 1985-93. Order wear rod # 015-420P. For a wider ski order Part No. 10-58

**PART NO. 10-76/B0544** **SUG. RETAIL \$74.00**

#### SKI DOO

Replaces Bombardier #505-0427/0613-00




Replaces ski used on Citation/E 1989-91; Citation LS/LSE 1985-88; Tundra 1985. Order wear rod # 015-414P.

**PART NO. 10-41/B0582** **SUG. RETAIL \$47.50**

#### SKI DOO

Replaces #505-0603-00



Replaces ski used on Safari Deluxe/Rally 1993-94; Safari L/LE/LCE/LX/LXE 1990-94; Safari GLX/LC 1990-92; Skandic II 1992-94. Order wear rod # 015-420P.

**PART NO. 10-75/B5944** **SUG. RETAIL \$74.95**

#### SKI DOO

Replaces #505-0666-10




Replaces ski used on Formula MXZ 440/583/670 1996-97; MXZ 440 1998.

**PART NO. 10-77/B0563** **SUG. RETAIL \$60.95**

#### YAMAHA

Replaces #8F3-23710-00  
4-5/8" wide




Replaces ski used on Bravo 1982-93, 96, 98-00; Enticer 1977-84; Excel III 1981-84. Order wear rod # 015-609P.

**PART NO. 10-29/B0512** **SUG. RETAIL \$35.95**

#### YAMAHA

Replaces #88F-23710-00/01  
5-3/4" wide




Replaces ski used on Exciter II 1991-93; Phazer 1991-97. Order wear rod # 015-614P.

**PART NO. 10-68/B0574** **SUG. RETAIL \$79.95**

#### SKI DOO

Replaces #505-0639-10




Replaces ski used on Formula 500 1997-99; Formula S/SL/SLS 1995-99; Grand Touring 500 1996; Skandic 380/440/500 1996-00; Touring E/LE/ SLE 1995-98.

**PART NO. 10-78/B5973** **SUG. RETAIL \$63.25**

#### YAMAHA

Replaces #8V0-23710-02-00  
5-3/4" wide



Replaces ski used on Phazer 1984-89.

Order wear rod # 015-614P.

**PART NO. 10-62/B0554** **SUG. RETAIL \$75.95**