


Skis - Cont.

All Skis Are Black Enamel

Wear Rod Not Included

YAMAHA

Replaces #86M-23710-00
5-3/4" wide



Replaces ski used on Exciter 1987-88; SRV 1987-91; V-Max 1987.
Order wear rod # 015-619P.

PART NO. 10-64/B5984 SUG. RETAIL \$79.95

YAMAHA

Replaces #8K4-23710-00, 8Y3-23710-00
5-1/8" wide



Replaces ski used on Enticer 340 and Excel III 1985-88; SS440 1980-85. Order wear rod # 015-610P.

PART NO. 10-61/B0562 SUG. RETAIL \$43.95

YAMAHA

Replaces 8AB-23710-01



Replaces ski used on V-Max 500/600 1994-96.

PART NO. 10-70/B0545 SUG. RETAIL \$89.95

UNIVERSAL

5-1/4" wide




This ski is 5-1/4" wide and fits a 2" wide leaf spring with center to center dimensions of 23.5", 24", 24.5", 25", 25.5", 26" and 26.5". Overall length is 41-1/2" with shock bracket. Fits nearly all snowmobiles. Order wear rod # 015-102P.

PART NO. 10-17/B0562 SUG. RETAIL \$43.95



YAMAHA

Replaces #8L0/8M6/8X6-23710-00
5-3/4" wide



Replaces ski used on SRV 1980-86; SRX 1981; V-Max 1983-86. Order wear rod # 015-614P.

PART NO. 10-63/B5994 SUG. RETAIL \$79.95

YAMAHA

Replaces #8E3-23710-09
5-3/8" wide



Replaces ski used on Bravo 250TS 1984; 250T 1994-95, 97; 250 TF 2001; Enticer 340T/TR, 400TR 1982-90; Exciter all 1976-81; GP440 1976-78; GS300 1976-77; GS340 1976-78; PR440 1976; STX 340/440 1976-77. Order wear rod # 015-608P.

PART NO. 10-28/B5942 SUG. RETAIL \$41.50

YAMAHA

Replaces #8Y7-23710-00



Replaces ski used on XLV (XL540) 1985-90. Order wear rod # 015-614P.

PART NO. 10-72/B5992 SUG. RETAIL \$49.95