

Skis

All Skis Are Black Enamel

Wear Rod Not Included



ARCTIC CAT

Replaces #0703-001/-028/041/129
5-1/2" wide



Replaces ski used on Bearcat 340 1995; Cheetah 1986-88, 93-94; Cheetah Touring 1988-92; Cougar 1985-92, 95-97; Cougar Mt. Cat 90, 95, 97; Cougar 2-Up 1991-92/96; El Tigre AFS/EXT/Mt. Cat/Special 1985-91; EXT/580/Dlx.ER/Mt. Cat 1994-97; EXT 580 EFI 1998; Jag AFS/Dlx./LT/Special 1989-93; Jag/Jag Dlx. 1997; Lynx/DLX/Mt. Cat 1991-93; Pantera 1986-88, 90, 95; Panther/DLX/Mt. Cat 1990-91; Panther/DLX/Liq. 1996; Panther 440, 550 1997; Panther 550 1998; Prowler 2-Up 1995; Puma/Dlx./2-Up 1997; Thunder Cat/Mt. Cat 1993-95; Wildcat 650/Mt. Cat 1988-90; Wildcat 1991, 95-96; Wildcat Mt. Cat 1991, 95; Wildcat EFI/Mt. Cat 1992; Wildcat Touring 1995-96. Order wear rod # 015-110P.

PART NO. 10-59/B5973

SUG. RETAIL \$63.25

ARCTIC CAT

Replaces #0703-119




Replaces ski used on Cougar/Mt. Cat 1993-94; EXT Special 1991; EXT/Mt. Cat 1992; EXT 580/580Z 1993; Jag/DLX 1992-96; Jag Liquid 1996; Pantera 1991-94; Panther/DLX 1992-95; Prowler/Mt. Cat 1991-93; Prowler Special 1991; Prowler 2-Up 1991-92; Puma/DLX 1995-96; Puma 2-Up 1995-96; Wildcat EFI 1994. Order wear rod # 015-115P.

PART NO. 10-69/B5984

SUG. RETAIL \$81.50

ARCTIC CAT

Replaces #0103-128/290, 0703-043
5-3/4" wide



Replaces ski used on Cross Country El Tigre 1979; El Tigre 1975-81/84; El Tigre Z 1975; Jag/DLX 1980-81/85-90; Jag LT 1981; Jag Mt. Cat 1990-91; Pantera 1979, 81, 85, 89; Panther 1980-81/84-89; Super Jag 1987-92; Z 1976-77. Order wear rod # 015-102P.

PART NO. 10-08/B5962

SUG. RETAIL \$44.95

ARCTIC CAT

Replaces #0703-052/-180




Replaces ski used on EXT Special 1992; EXT 580Z 1993; Jag Special 1992; Jag Z 1993-94; Prowler 1990; Prowler Special 1992; Wildcat/Wildcat Mt. Cat 1992; Wildcat 700/EFI 1993. Order wear rod # 015-118P.

PART NO. 10-60/B5983

SUG. RETAIL \$64.95

ARCTIC CAT

Replaces #0103-073
5-9/16" wide



Replaces ski used on Cheetah 1972-75; Cougar 1986; El Tigre 1973-74; EXT 1972-73; Jag 1975; Lynx 1971-75; Pantera 1975; Panther 1967-75; Puma 1972-73; VIP 1974. Order wear rod # 015-102P. This ski is also replaced by our # 10-06 ski.

PART NO. 10-03/B5962

SUG. RETAIL \$44.95

ARCTIC CAT

Replaces #0103-129, 0703-068
5-3/4" wide



Replaces ski used on Cheetah, Jag and Panther 1976-79; Lynx 1976-80. Order wear rod # 015-102P.


PART NO. 10-06/B5942

SUG. RETAIL \$41.50

MOTO SKI

SKI DOO

Replaces Bombardier #505-0371-00
5-1/2" wide



Replaces ski used on Blizzard 1979-84 (except 5500 MX 1982-84); Everest 1979-82; Futura 400/440/444 LC 1979; Grand Prix Special 1979; RV 1977-79; Super Sonic/Cross Country 1979; TNT 1976-78. Order wear rod # 015-418P.

PART NO. 10-33/B5992

SUG. RETAIL \$49.95

MOTO SKI

SKI DOO

Replaces Bombardier #505-0281/0282-00
4-9/16" wide



Replaces ski used on Moto Ski Mirage 1980-83; Ski Doo Citation 1980-84; RV Cross Country 1979. Order wear rod # 015-414P.

PART NO. 10-19/B0522

SUG. RETAIL \$37.50

Skis

All Skis Are Black Enamel

Wear Rod Not Included



ARCTIC CAT

Replaces #0703-001/-028/041/129
5-1/2" wide



Replaces ski used on Bearcat 340 1995; Cheetah 1986-88, 93-94; Cheetah Touring 1988-92; Cougar 1985-92, 95-97; Cougar Mt. Cat 90, 95, 97; Cougar 2-Up 1991-92/96; El Tigre AFS/EXT/Mt. Cat/Special 1985-91; EXT/580/Dlx.ER/Mt. Cat 1994-97; EXT 580 EFI 1998; Jag AFS/Dlx./LT/Special 1989-93; Jag/Jag Dlx. 1997; Lynx/DLX/Mt. Cat 1991-93; Pantera 1986-88, 90, 95; Panther/DLX/Mt. Cat 1990-91; Panther/DLX/Liq. 1996; Panther 440, 550 1997; Panther 550 1998; Prowler 2-Up 1995; Puma/Dlx./2-Up 1997; Thunder Cat/Mt. Cat 1993-95; Wildcat 650/Mt. Cat 1988-90; Wildcat 1991, 95-96; Wildcat Mt. Cat 1991, 95; Wildcat EFI/Mt. Cat 1992; Wildcat Touring 1995-96. Order wear rod # 015-110P.

PART NO. 10-59/B5973

SUG. RETAIL \$63.25

ARCTIC CAT

Replaces #0703-119



Replaces ski used on Cougar/Mt. Cat 1993-94; EXT Special 1991; EXT/Mt. Cat 1992; EXT 580/580Z 1993; Jag/DLX 1992-96; Jag Liquid 1996; Pantera 1991-94; Panther/DLX 1992-95; Prowler/Mt. Cat 1991-93; Prowler Special 1991; Prowler 2-Up 1991-92; Puma/DLX 1995-96; Puma 2-Up 1995-96; Wildcat EFI 1994. Order wear rod # 015-115P.

PART NO. 10-69/B5984

SUG. RETAIL \$81.50

ARCTIC CAT

Replaces #0103-128/290, 0703-043
5-3/4" wide



Replaces ski used on Cross Country El Tigre 1979; El Tigre 1975-81/84; El Tigre Z 1975; Jag/DLX 1980-81/85-90; Jag LT 1981; Jag Mt. Cat 1990-91; Pantera 1979, 81, 85, 89; Panther 1980-81/84-89; Super Jag 1987-92; Z 1976-77. Order wear rod # 015-102P.

PART NO. 10-08/B5962

SUG. RETAIL \$44.95

ARCTIC CAT

Replaces #0703-052/-180



Replaces ski used on EXT Special 1992; EXT 580Z 1993; Jag Special 1992; Jag Z 1993-94; Prowler 1990; Prowler Special 1992; Wildcat/Wildcat Mt. Cat 1992; Wildcat 700/EFI 1993. Order wear rod # 015-118P.

PART NO. 10-60/B5983

SUG. RETAIL \$64.95

ARCTIC CAT

Replaces #0103-073
5-9/16" wide



Replaces ski used on Cheetah 1972-75; Cougar 1986; El Tigre 1973-74; EXT 1972-73; Jag 1975; Lynx 1971-75; Pantera 1975; Panther 1967-75; Puma 1972-73; VIP 1974. Order wear rod # 015-102P. This ski is also replaced by our # 10-06 ski.

PART NO. 10-03/B5962

SUG. RETAIL \$44.95

ARCTIC CAT

Replaces #0103-129, 0703-068
5-3/4" wide



Replaces ski used on Cheetah, Jag and Panther 1976-79; Lynx 1976-80. Order wear rod # 015-102P.


PART NO. 10-06/B5942

SUG. RETAIL \$41.50

MOTO SKI

SKI DOO

Replaces Bombardier #505-0371-00
5-1/2" wide



Replaces ski used on Blizzard 1979-84 (except 5500 MX 1982-84); Everest 1979-82; Futura 400/440/444 LC 1979; Grand Prix Special 1979; RV 1977-79; Super Sonic/Cross Country 1979; TNT 1976-78. Order wear rod # 015-418P.

PART NO. 10-33/B5992

SUG. RETAIL \$49.95

MOTO SKI

SKI DOO

Replaces Bombardier #505-0281/0282-00
4-9/16" wide



Replaces ski used on Moto Ski Mirage 1980-83; Ski Doo Citation 1980-84; RV Cross Country 1979. Order wear rod # 015-414P.

PART NO. 10-19/B0522

SUG. RETAIL \$37.50

Skis - Cont.


All Skis Are Black Enamel

Wear Rod Not Included



MOTO SKI SKI DOO


Replaces Bombardier #505-0630-00
139mm wide



Replaces ski used on Formula Mach I/XTC/II 1990-93; Formula MX LT/XTC/XTCE/XTCR 1991-93; Formula Plus/LT 1989-90; Formula Plus/XTC/XTCE 1991-93. This ski is an exact replica of MXLT/Plus LT ski - 22mm wider than standard models for extra flotation. Order wear rod # 015-420P. For a narrower ski order Part No. 10-76.
PART NO. 10-58/B0534 **SUG. RETAIL \$72.50**

MOTO SKI SKI DOO

Replaces Bombardier #505-0184/0192/0268/0615-00
5-1/4" wide



Replaces ski used on Moto Ski Mirage 1979; Spirit 1976-83; Ski Doo Citation 1978-79; Elan 1976-96. Order wear rod # 015-401P.
PART NO. 10-32/B5952 **SUG. RETAIL \$43.25**

POLARIS


Replaces #1820333



Replaces ski used on 1992-98 Indy Lite/Dlx/GT; Indy 340/Dlx/Touring 1999-02. Indy Starlite/GT 1991-95. Order wear rod #015-246P.
PART NO. 10-79/B0554 **SUG. RETAIL \$75.95**

POLARIS

Replaces #1820332
1820232/45/51/52/54/64/65/68/79




Replaces ski used on Indy models 1980-92; Indy 440 XCR 1993-96; Indy 500/EFI/SKS/Classic/Touring 1993-96; Indy RXL/SKS/Touring 1993-96; Indy XLT/SKS/SP/Touring 1993-96; Indy XLT Special 1993-94; Indy 440/SKS 1993-95; Indy 600 XCR 1995; Sport/SKS/Touring 1993-96; Super Sport 1994-97; Trail/DLX 1993-96; Storm/SKS 1993-95; 500 Widetrak/GT/LX 1993-96; Ultra/SKS/SP 1996; XCR 600/ XCR-SP 1996. Order wear rod # 015-246P.

PART NO. 10-39/B5914 **SUG. RETAIL \$69.95**

MOTO SKI SKI DOO

Replaces Bombardier #505-0407/0424/0552
5-3/8" wide



Replaces ski used on Moto Ski Sonic LC 1984; Mirage III 1985; Ski Doo Formula SP 1985-86; Formula SS 1985; Safari 377/447/503/Grand Luxe/Saga 1984-90; Skandic 503 1986; SS25 1984; Tundra/LT 1985-89. Order wear rod # 015-401P.
PART NO. 10-57/B5922 **SUG. RETAIL \$38.25**

POLARIS


Replaces #11820175/246/255



Replaces ski used on Apollo 1979-80; Centurion 500 1979-80; Charger 1969-73; Cobra 1978-79; Colt 1969/72-78; Custom/II 1973-74; Cutlass/SS 1981-82; Electra 1974-77; Galaxy 1981-82; Gemini 1979-81; Long Track 1984-85; Mustang 1969-73; Playmate 1970-71; Sport 440 1983; SS 340 1978; SS 440 1083-85; Star 1983-85; Starfire 1976; TX 1973-80; TXC 1979-82; TX Charger/Racer 1971; TX-L 1977-82; Voyageur 1970. Order wear rod #015-102P.
PART NO. 10-07/B5912 **SUG. RETAIL \$36.50**

POLARIS


Replaces #1820175/1820246/1820255
5-1/2" wide



Replaces ski used on Long Track 1986-87; Sprint/ES 1986-89; SS 1986; Star 1986-89; Star Trak 1987. Order wear rod # 015-246P. This ski is also replaced by our # 10-07 ski.
PART NO. 10-38/B0951 **SUG. RETAIL \$27.70**

POLARIS

Replaces #1820430-067



Replaces ski used on Indy 440/XCF 1998; Indy 500 EFI/SKS 1998-02; Indy 600 XC/XCR 1998; Classic Touring 1998; LTD Spec. 1997-98; Indy RXL 1998; Indy Sport 1998-99; Indy Sport Touring/es 1998-02; Indy Super Sport 1998-02; Indy Trail 1998-99; Indy Trail Touring/Transport 1998-00; Indy Ultra SP/Touring 1998; Ultra/Ultra SPX 1998; Indy Wide Track LX 1998-02; XLT Classic/LTO Special/Touring 1998; XLT SKS 1999; XLT SP 1997-98.

PART NO. 10-81/B5954 **SUG. RETAIL \$76.50**

Skis - Cont.

All Skis Are Black Enamel

Wear Rod Not Included



SKI DOO


Replaces 505-0628-00
117 mm. wide



Replaces ski used on Formula Mach (all) 1989-93; Formula MX (all Except XTCR) 1985-93; Formula Plus (all) 1985-93. Order wear rod # 015-420P. For a wider ski order Part No. 10-58
PART NO. 10-76/B0544 **SUG. RETAIL \$74.00**

SKI DOO


Replaces #505-0603-00



Replaces ski used on Safari Deluxe/Rally 1993-94; Safari L/LE/LCE/LX/LXE 1990-94; Safari GLX/LC 1990-92; Skandic II 1992-94. Order wear rod # 015-420P.
PART NO. 10-75/B5944 **SUG. RETAIL \$74.95**

YAMAHA


Replaces #8F3-23710-00
4-5/8" wide



Replaces ski used on Bravo 1982-93, 96, 98-00; Enticer 1977-84; Excel III 1981-84. Order wear rod # 015-609P.
PART NO. 10-29/B0512 **SUG. RETAIL \$35.95**

YAMAHA

Replaces #88F-23710-00/01
5-3/4" wide



Replaces ski used on Exciter II 1991-93; Phazer 1991-97. Order wear rod # 015-614P.
PART NO. 10-68/B0574 **SUG. RETAIL \$79.95**

SKI DOO

Replaces Bombardier #505-0427/0613-00



Replaces ski used on Citation/E 1989-91; Citation LS/LSE 1985-88; Tundra 1985. Order wear rod # 015-414P.
PART NO. 10-41/B0582 **SUG. RETAIL \$47.50**

SKI DOO


Replaces #505-0666-10



Replaces ski used on Formula MXZ 440/583/670 1996-97; MXZ 440 1998.
PART NO. 10-77/B0563 **SUG. RETAIL \$60.95**

SKI DOO

Replaces #505-0639-10



Replaces ski used on Formula 500 1997-99; Formula S/SL/SLS 1995-99; Grand Touring 500 1996; Skandic 380/440/500 1996-00; Touring E/LE/ SLE 1995-98.
PART NO. 10-78/B5973 **SUG. RETAIL \$63.25**

YAMAHA

Replaces #8V0-23710-02-00
5-3/4" wide



Replaces ski used on Phazer 1984-89.
Order wear rod # 015-614P.
PART NO. 10-62/B0554 **SUG. RETAIL \$75.95**

Skis - Cont.


All Skis Are Black Enamel

Wear Rod Not Included



YAMAHA

Replaces #86M-23710-00
5-3/4" wide



Replaces ski used on Exciter 1987-88; SRV 1987-91; V-Max 1987.
Order wear rod # 015-619P.

PART NO. 10-64/B5984 SUG. RETAIL \$79.95

YAMAHA

Replaces #8K4-23710-00, 8Y3-23710-00
5-1/8" wide



Replaces ski used on Enticer 340 and Excel III 1985-88; SS440 1980-85. Order wear rod # 015-610P.

PART NO. 10-61/B0562 SUG. RETAIL \$43.95

YAMAHA

Replaces 8AB-23710-01



Replaces ski used on V-Max 500/600 1994-96.

PART NO. 10-70/B0545 SUG. RETAIL \$89.95

UNIVERSAL

5-1/4" wide




This ski is 5-1/4" wide and fits a 2" wide leaf spring with center to center dimensions of 23.5", 24", 24.5", 25", 25.5", 26" and 26.5". Overall length is 41-1/2" with shock bracket. Fits nearly all snowmobiles. Order wear rod # 015-102P.

PART NO. 10-17/B0562 SUG. RETAIL \$43.95

YAMAHA

Replaces #8L0/8M6/8X6-23710-00
5-3/4" wide




Replaces ski used on SRV 1980-86; SRX 1981; V-Max 1983-86. Order wear rod # 015-614P.

PART NO. 10-63/B5994 SUG. RETAIL \$79.95

YAMAHA

Replaces #8E3-23710-09
5-3/8" wide



Replaces ski used on Bravo 250TS 1984; 250T 1994-95, 97; 250 TF 2001; Enticer 340T/TR, 400TR 1982-90; Exciter all 1976-81; GP440 1976-78; GS300 1976-77; GS340 1976-78; PR440 1976; STX 340/440 1976-77. Order wear rod # 015-608P.

PART NO. 10-28/B5942 SUG. RETAIL \$41.50

YAMAHA

Replaces #8Y7-23710-00



Replaces ski used on XLV (XL540) 1985-90. Order wear rod # 015-614P.

PART NO. 10-72/B5992 SUG. RETAIL \$49.95